

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

HAER  
CAL,  
SS-DARD.V,  
1-

**Middle Fork Stanislaus River Bridge**  
(Dardanelle Bridge)  
Spanning Middle Fork Stanislaus River  
on California State Highway 108  
Dardanelle vicinity  
Tuolumne County  
California

HAER No. CA-72

NOTE: The following photographs were taken by Don Tateishi, photographer, July 1989

- CA-72-1      CONTEXTUAL VIEW OF BRIDGE IN ITS SETTING, LOOKING NORTHWEST  
FROM UPSTREAM
- CA-72-2      CONTEXTUAL VIEW OF BRIDGE IN ITS SETTING, LOOKING SOUTHEAST  
FROM DOWNSTREAM
- CA-72-3      CONTEXTUAL VIEW OF BRIDGE IN ITS SETTING, LOOKING SOUTHEAST  
FROM DOWNSTREAM
- CA-72-4      OBLIQUE VIEW OF UPSTREAM ELEVATION, LOOKING NORTHWEST
- CA-72-5      OBLIQUE VIEW OF UPSTREAM ELEVATION, LOOKING WEST-NORTHWEST
- CA-72-6      VIEW OF DOWNSTREAM ELEVATION, LOOKING SOUTHEAST
- CA-72-7      VIEW OF DOWNSTREAM ELEVATION, LOOKING SOUTHEAST
- CA-72-8      APPROACH VIEW TO BRIDGE, LOOKING EAST-NORTHEAST
- CA-72-9      APPROACH VIEW TO BRIDGE, LOOKING WEST SOUTHWEST
- CA-72-10     VIEW OF UNDERSTRUCTURE, SHOWING TIMBER SCISSORS TRUSS, FLOOR  
BEAMS, AND WOODEN DECK SOFFIT, LOOKING WEST-SOUTHWEST
- CA-72-11     DETAIL VIEW OF UNDERSTRUCTURE, SHOWING TIMBER TRUSS END POSTS  
AND TOP CHORD, TENSION RODS, AND TRUSS FOOTINGS, LOOKING  
NORTHEAST
- CA-72-12     DETAIL VIEW OF UNDERSTRUCTURE, SHOWING TIMBER TRUSS END POSTS,  
TOP CHORD, GUSSET PLATES, TENSION RODS, TRANSVERSE BEAM, AND  
FLOOR BEAM, LOOKING NORTHEAST

Middle Fork Stanislaus River Bridge  
(Dardanelle Bridge)  
HAER No. CA-72  
Index to Photographs  
(Page 2)

- CA-72-13      DETAIL VIEW OF UNDERSTRUCTURE, SHOWING WEST ABUTMENT, FLOOR BEAMS, AND WOODEN DECK SOFFIT, LOOKING WEST-SOUTHWEST
- CA-72-14      DETAIL VIEW OF BRIDGE, LOOKING NORTH, SHOWING DAMAGE TO FLOOR BEAMS AND DECK OF WEST APPROACH SPAN, CAUSED WHEN CONTRACTOR'S FORCES, WORKING ON ADJACENT ABUTMENT FOR REPLACEMENT BRIDGE, DYNAMITED GRANITE BOULDERS INTO UPSTREAM SIDE OF HISTORIC BRIDGE
- CA-72-15      DETAIL VIEW OF UNDERSTRUCTURE, SHOWING DAMAGE TO FLOOR BEAMS AND DECK OF WEST APPROACH SPAN, LOOKING EAST
- CA-72-16      DETAIL VIEW OF DAMAGED AREA OF WEST APPROACH SPAN, SHOWING REMAINING GRANITE OUTCROP BEING BROKEN UP BY HYDRAULIC HAMMER MOUNTED ON A BACKHOE, LOOKING EAST-NORTHEAST
- CA-72-17      DETAIL VIEW SHOWING METAL DECK PLATES COVERING DAMAGED AREA OF WEST APPROACH SPAN
- CA-72-18      DETAIL VIEW OF DAMAGED AREA OF WEST APPROACH SPAN, SHOWING GRANITE OUTCROP BEING REMOVED, LOOKING EAST-SOUTHEAST
- CA-72-19      OVERVIEW SHOWING REMOVAL OF GRANITE OUTCROP, FOLLOWING DAMAGE TO BRIDGE, LOOKING NORTHEAST
- CA-72-20      DETAIL VIEW SHOWING REMOVAL OF GRANITE OUTCROP, FOLLOWING DAMAGE TO BRIDGE, LOOKING NORTHEAST